

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

**Translation of 'Consigne de Navigabilité' ref. : 96-114(A)
In case of any difficulty, reference should be made to the French original issue.**

CHAIZE

CS and JZ type balloons

Suspension cables

This Airworthiness Directive concerns CHAIZE hot air balloons following :

CAT 1 : JZ type, all models, S/N 139 to 142
CS type, all models, S/N 61, 67, 80, 93 and 108

CAT 2 : JZ type, all models, S/N 118, 120 to 122, 125 to 138
CS type, all models, S/N 46, 47, 51, 52, 58, 78, 93, 123
and THUNDER AND COLT hot air balloons AX7-77 S/N 1515 and AX7-65 S/N 335.

This AD is following Telegraphic AD T-96-114(A)R1 dated June 12, 1996 and made mandatory the following measures at the effective date of this AD :

- **Before the next flight**
 - a) Balloons of CAT 1 : Replace suspension cables in accordance with CHAIZE SB N° 01.
 - b) Balloons of CAT 2 : Inspect the crimping of cables in accordance with CHAIZE SB N° 01. In case of fault replace the defective cables.

(a) and (b) measures must be applied by technical personnel of the manufacturer.

Application of (a) and (b) measures permit balloons return to service after stopping by AD T-96-114(A) dated June 10, 1996.

Record the application of this AD in the balloon logbook.

REF. : CHAIZE SB N° 01 dated June 12, 1996

This AD replaces the telegraphic AD T-96-114(A)R1 dated June 12, 1996.

EFFECTIVE DATE : JUNE 12, 1996
(same as the Telegraphic AD T-96-114(A)R1)

v/JB

July 03, 1996	CHAIZE CS and JZ type balloons	96-114(A)
---------------	-----------------------------------	-----------